




9 Essential Steps of Forklift Battery Care

Proper care extends battery life, powers better forklift performance, and keeps your team safe — **Move It...with Apex!**

1. Add approved water only; never acid.
2. Keep electrolyte level above separator protectors.
3. Keep battery top clean & dry.
4. Keep flame & metal away from battery top.
5. Keep vent caps tightly in place.
6. Cool before charging or operating if battery is above 115°F.
7. Charge only at proper voltage and apere hours.
8. Keep truck compartment and battery cover open during charging.
9. When in doubt, contact your local Apex material handling battery professional.



Pro Tips from the Apex Battery Experts

- Add water to the manufacturer's indicated levels at the **END OF CHARGE CYCLE**.
- Filling to this level before charging will lead to acid overflow.
- Acid attacks external battery parts.
- Any acid loss from the battery results in power loss.

More than just forklifts. Find all your warehouse vehicles and service needs at Apex!

Find It at Apex.

